

Release notes history

V1.0.1	09/11/5	<ol style="list-style-type: none"> 1. In UR Mode, when device connect to specified remote AP, the repeater AP will automatically change channel as same of remote APs' 2. In CB/UR, Add 『Lock MAC to AP』 option on Station Profiles page 3. Fixed all WEP key length on GUI 4. Add Parental Control function
V1.0.2	09/12/16	<ol style="list-style-type: none"> 1. Fixed Max. wireless clients driver bug (When wireless clients actual link more than Max. settings on GUI, the system automatiacly reboot)
V1.0.3	09/11/10	<ol style="list-style-type: none"> 1. Add 『Enable/Disable』 option on Repeater AP page
V1.0.4	10/1/11	<ol style="list-style-type: none"> 1. Add 『Router AP』 and 『CPE+AP』 Mode in Operating page 2. Add 『Ping Watchdot』 function 3. Add 『PPTP』 function on WAN page 4. Fixed QoS Layer-7 protocol bug 5. Fixed QoS and Parental Control bug (When specify protocl to 『Any』 , the port rule will be failed)
V1.0.5	10/2/5	<ol style="list-style-type: none"> 1. Fixed QoS Plot, the plot will auto refresh per 180s

		2. Add 『Slot Time』 and 『ACK Timeout』 option for long distance
V1.0.6	10/2/10	1. Add 『Channel』 option on Station profiles page
V1.0.7	10/2/12	1. Fixed connection crash with Mikrotik's AP
V1.0.8	10/2/25	1. Show apply message when click connect button on Station Profile page
V1.0.9	10/3/3	1. Fixed MAT bug on CB/UR mode (When local client connect to remote pppoe server)
V1.0.10	10/3/22	<ol style="list-style-type: none"> 1. Add Wizard Setup function 2. Change CPE's Station Profile page, it will be the same with CB/UR Mode 3. Add 『Country』 code on CPE mode 4. Fixed 『Blank Space』 bug on ESSID setting field 5. Fixed 『Escape』 character problem on GUI 6. Pre-shared key does not support 『;』 character on Station Profile page.(Driver does not support) 7. Add ASCII characters in all Description, Comment fields 8. Add Admin' password length verify on GUI 9. Remove STP on GUI (The system always ON)

		10. Fixed last WDS's MAC address field bug 11. Fixed Pure WDS Mode bug (When all of WDS MACs do not setting, the wireless clients can scan ESSID)
V1.0.11	10/4/12	1. Add Channel 165 on None and US Country code
		2. Fixed telnet session problem
V1.0.12	10/5/14	1. Add auto connection function on CB+UR Mode (When Remote Main AP change channel, the device will automatically change channel and connect to Remote Main AP)
		2. Add auto select Wireless Profile function on CPE Mode and CB+UR Mode(When device can't connect with correctly Wireless Profile, the device will use next Wireless profile around 60s)
V1.0.13	10/6/11	1. Fixed High channel can't link AR5414
V1.0.14	10/7/30	1. Fixed Default Gateway can't work on CPE mode. 2. Fixed STP issue
V1.0.15	10/8/11	1. Add SIP, H.323, TFTP Pass-Through on NAT